EXISTING BUILDING: LIMITED REMODEL

Building Repair: FACILITY IMPROVEMENTS PER 2016 ASSESSMENT BY ALTUSWORKS







EXISTING CORRIDOR



EXISTING FLOODED BUILDING ENTRY



EXISTING MULTI-PURPOSE ROOM WATER DAMAGE



EXISTING MEETING ROOM

EXISTING MEETING ROOM




EXISTING LEAKING PLANTER



EXISTING RESTROOM

Ground Floor



CLARENDON COMMUNITY CENTER PARK